

R-035B

MAXFIELD ST
New Bedford

Inspection Status: Remote Inspection
Inspection Level: Level 2

| | Quick | Index | Rating |
|------------|-------|-------|--------|
| Overall | 221B | 1.1 | 19 |
| Structural | 2215 | 1.3 | 9 |
| O&M | 1A00 | 1 | 10 |

Project: | New Bedford 3D Regulator Inspections

Owner: | New Bedford, MA

Customer: CCDM Smith

MANHOLE

MH Use: | Sanitary

Year Constructed:

Evidence of Surcharge: No

Access Type: Manhole

Year Renewed:

MEASUREMENTS

Rim to Invert: 7.5ft

Northing:

GPS Accuracy:

Rim to Grade:

Easting:

Additional Information:

Grade to Invert: 7.5ft

Elevation:

Rim to Grade Exposed:

Vertical Datum:

COVER

Type: Vented

Center Cover Size:

Bearing Surface Diameter: 25.5"

Shape: Circular

Cover Material: Cast Iron

Bearing Surface Width: 1"

Size: 23.5"

Hole Diameter: <= 1/2 inch
(10mm)

Cover/Frame Fit: Good

Size Width:

Hole Number: 4

Cover Condition: Sound

COVER INSERT

Insert Type: None

Insert Condition:

COVER ADJUSTMENT RING

Ring Type: Solid

Ring Condition: Sound

Ring Material: Cast Iron

Ring Height:

FRAME

Frame Material: Cast Iron

Clear Opening Width: 21"

Seal Inflow: None

Bearing Surface Width: 1"

Frame Depth:

Frame Condition: Sound

Bearing Surface Depth: 6"

Offset Distance:

Clear Opening Diameter: 21"

Seal Condition: Sound



CHIMNEY

Chimney Present: Yes

Chimney Depth: 0.4ft

Clear Opening:

Chimney I/I:

First Material: Concrete (precast)

Second Material:

Lining Interior:

Lining Exterior:

Chimney Condition:

CONE

Cone Depth: 2.5ft

Cone Type: Conical centered

Clear Opening:

First Material: Concrete (precast)

Second Material:

Lining Interior:

Lining Exterior:

Cone Condition:

WALL

Wall Diameter:

Wall Width:

Wall Depth: 4ft

First Material: Concrete (precast)

Second Material:

Lining Interior:

Lining Exterior:

Wall Condition:

BENCH

Bench Present: Yes

Material: Concrete (precast)

Lining:

Bench Condition:

CHANNEL

Channel Present: No

Material:

Type:

Exposure:

Channel Condition:

STEP

Number: 0

Material:

PIPE CONNECTION INFORMATION

| Pipe No. | Clock | Rim to Inv. | Direction | Material | Shape | Height | Width | Cond. | Seal Cond. | Pipe Type | Struct. ID | Comments |
|----------|-------|-------------|-----------|--------------------------------|----------|--------|-------|-------|------------|--------------------|------------|----------|
| 1 | 6 | 6" | Out | Vitrified Clay Pipe | Circular | 12" | | Sound | Sound | Gravity Connection | | |
| 2 | 12 | 6" | In | Concrete Pipe (non-reinforced) | Circular | 24" | | Sound | Sound | Gravity Connection | | |
| 3 | 9 | 4" | In | Vitrified Clay Pipe | Circular | 6" | | Sound | Sound | Gravity Connection | | |
| 4 | 5 | 7.3" | Out | Concrete Pipe (non-reinforced) | Circular | 24" | | Sound | Sound | Gravity Connection | | |
| 5 | 5 | 5" | In | Vitrified Clay Pipe | Circular | 4" | | Sound | Sound | Gravity Connection | | |
| 6 | 6 | 2.3" | In | Concrete Pipe (non-reinforced) | Circular | 8" | | Sound | Sound | Gravity Connection | | |
| 7 | 2 | 2.4" | In | Vitrified Clay Pipe | Circular | 8" | | Sound | Sound | Gravity Connection | | |

GENERAL INFORMATION

Surveyed By:

Reviewed By: M. Bierman


Reviewer Number: P0035145122021

Precleaning: No Pre-Cleaning

Sheet No.:

Date Cleaned:

Condition Report





Code: **MGO**
Description: **Miscellaneous General Observation**

Distance: **0ft**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within Eight" of Joint: **False**
Remarks: **Start inspection**



Code: **MMS**
Description: **Missing Mortar Small**

Distance: **1ft**
Structural Grade: **2**
O&M Grade: **0**
Clock Start/From: **1**
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within Eight" of Joint: **False**
Remarks:



Code: **SAV**
Description: **Surface Damage Aggregate Visible**

Distance: **5ft**
Structural Grade: **2**
O&M Grade: **0**
Clock Start/From: **12**
Clock To: **12**
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within Eight" of Joint: **False**
Remarks:



Code: **MGO**
Description: **Miscellaneous General Observation**

Distance: **6ft**
Structural Grade: **0**
O&M Grade: **0**
Clock Start/From:
Clock To:
1st Value:
2nd Value:
Value Percent:
Continuous Index:
Within Eight" of Joint: **False**
Remarks: **End inspection**

