CSO SPEC SHEET

Structure #: REG 027 A

Date: 12/20/2012

Insp. By: AK & AH

Structure Type: Broken Pipe Structure DIM's:			oe: Block Regulator	
Size of Sewer Pipe: Size of Storm Drain Pipe: Sewer Direction: North to South	Rim to Weir Wall: Rim to Storm Drain Invert: Rim to Top of Sewer (Normal Flow): Free Board:			
Over All Rating: (Circle One)	Poor	Fair Good	Excellent	
Comments:				
Field Sketch:				
* N				
	Mill Rd.			
4				
250			ited st	

CSO FIELD PHOTOS

Structure#: REG 027 A

Location: Mill Rd. Between Mazeppa St. and Jireh St.

Figure 1.



Figure 2.



Figure 3.



Descriptions

Figure 1: View of Regulator 027 A. Facing North.

Figure 2: Inside view of manhole. A- Sewer; B- Weir Wall; C- Storm Drain.

Figure 3: Google Earth Image of location of Regulator 027 E. A- Reg 027A

CSO/Regulator Repair Log

Structure #: lea 527A

Needed Repair Description:	Date:	Completed Repairs	Date:
	-		
		\$.	