

APPLICATION No.: 1577

TAP CLEARED ✓

LOCATION: 101 So. Sixth

OWNER: Walter Kirwin

MEASURES:

5/8"

S from

E from W line

N from N line

Wing

So. Sixth

House

2.2 ft.

4/5 ft.

0.6 ft.

August 27, 1959 Rewiped joint at main.
1 lb. wiping solder

2/23/17 renewed main to meter
26 ft 3/4" copper tubing
1 ft 3/4" curb stop valve
1 ft cast iron curb stop boxes
1 ft 1/2" corp adapter
1 ft 3/4" copper male adapter
1 ft 3/4" 90° threaded copper
1 ft 3/4" ball valve
1 ft 3/4" x 1/2" brass bushing
lead worker - manny washburn dpi

DATE

BEF.

AFT.

REMARKS

8-27-59

Reamed

[illegible]

CHARGE OUTS

[illegible]

APPLICATION No.: 1577

TAP CLEARED ✓

LOCATION: 101 Wing So. Sixth S.W. Cor. Wing

OWNER:

MEASURES: 5/8"

H lead

Oct. 16, 1973

S from

Wing

2.2 ft.

E from W

Sixth

4.5 ft.

N from N

house

0.6 ft.

DATE

BEF.

AFT.

REMARKS

[illegible]

CHARGE OUTS

[illegible]

1577

101 So. Sixth St.

OWNER:

31-313

MEASURES:

S x S line Wing St.	2.2ft.
E x W Line Sixth St.	4.5ft.
N x N line House	0.6ft

Aug. 27, 1959: Ser. leak, rewiped joint at main
1Lb. wiping solder-1/2" tap reamed.
Compression Jaeger 1Hr.

TAP CLEARED

DATE _____

BEF.

AFT.

REMARKS

[illegible]

CHARGE OUTS

[illegible]