

3/22/2011 Service Killed

APPLICATION No.: 16271

TAP CLEARED

22756

LOCATION: 478 Union

OWNER: Hawes Electric

DATE BEF. AFT. REMARKS

5-27-99 Tap reamed

MEASURES: E from  $\frac{3}{4}$  L. Newton(north) 22.2 ft.  
N from S line Union 8.5 ft.  
No. from bldg.

June 4, 1974 Renewed from 6" outside curb stop to a point 5 ft. inside curb stop.

$5\frac{1}{2}$  ft. -  $\frac{3}{4}$ " Copper tubing  $\frac{3}{4}$ " Curb Stop  
2# wiping solder Stop Box

September 11, 1974 Renewed from the main to a point 1 ft. from the main.

1 ft. -  $\frac{3}{4}$ " Copper tubing 1 wipe joint  
 $\frac{3}{4}$ " x  $\frac{3}{4}$ " Fig. 413

Feb. 23, 1960 Renewed from curb stop to  $4\frac{1}{2}$  ft. inside curb stop.  
 $4\frac{1}{2}$  ft. of  $\frac{3}{4}$ " copper tubing 2 lb. wiping solder

5/27/99

M. Pavao Const. renewed from main to property line.  
Stock supplied by Contractor: 18 ft. -  $\frac{3}{4}$ " Copper tubing, 1 -  $\frac{3}{4}$ " Curb Stop, 1 - Caldwell Stop Box, 1 -  $\frac{5}{8}$ " x  $\frac{3}{4}$ " lead to cop. adapt. XXS, 1 -  $\frac{5}{8}$ " x  $\frac{3}{4}$ " Fig. 413. M. Pavao Cont. to maintain cut.

3/22/11 - RJ Canessa Killed this Service at the tap  
Inspected by Percy

[illegible]

## This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some minor discoloration and small dark spots, possibly due to age or handling. A faint horizontal line is visible near the top edge of the page.