LOCATION: W.S. 1489 Morton Ave., S x Meadow St.  OWNER: Euclide Tissette  Copper 5-21-48  DATE BEF. AFT. REMARKS  OWNER: SECONDER: AFT. REMARKS	48
OWNER: Bucilde Tissette	48
MEASURES: 3/4" Copper 5-21-48	
S from S line Meadow 34.7 ft.	
E from W line Morton Ave. 8.2 ft.	
12-12-75 S from N line House 7.0 ft.	
2/16/94 Repaired leak at tap. Installed a 10" Rockwell #239 tapped full circle clamp x 1"; 1" corp. tap, 1 ft 1" copper tubing,	
1 - 5/8" x 3/4" lead to cop. adapt XS (used as a reducer 1" x 3/4") - see main pipe report	
8-24-21	
S x S Line Meadow St 34.7'	
E x W Line Morton Ave 8.2' S x N Line House 6.0'	
N x S line house 14.0'	
E x E line house 67.5'	
Main to property line 14.0' Pipe inside property 63.0'	
C/S to nouse meter returned to show	
Contractor: WC Smith Inspector P. Reynolds	
service#34126 pulled on 5-13-2021: as a reconnection	
as a reconnection	

METE	RH	ISTO	PY							CHARGE OUTS
DATE		SIZE		NUMBER	READING	TEST			REMARKS	
	OUT									
6-25-48		3/4	Empire R 12	7870104				V <sub>1</sub>		
-										
									<u> </u>	
The state of the										
	,-					1		111111111111111111111111111111111111111		
							. 64.5			
				A STATE OF THE STA						
	3.2									
					3.7					
	-									
1000000										
								1		
	-							-		
)	-									
						The state of				
	-									
	-									