

APPLICATION No.: 23057

TAP CLEARED

LOCATION: N.S. 117 Rockdale Ave. W x HemlockOWNER: C. Motorá.*Auto Zone*

MEASURES: 1"

W from W line

S from N line

Copper

Avon

Rockdale

3-16-&17-50

52.7 ft.

8.2 ft.

DATE

BEF.

AFT.

REMARKS

11/21/03

Tap reamed

August 1982 Cement lined - off at curb stop

11/10/03 J.S. Luiz renewed service from curb stop to rear of building.

New measures:

W x W line Avon St.	53.0 ft.
S x N line Rockdale Ave.	10.0 ft.
E x W line building	26.0 ft.
W x E line building	34.0 ft.
S x S line building	80.0 ft.

11/21/03 Renewed from main to a point 2 ft. Stock:
 2 ft. 1" copper tubing; 1" x 1" cop-cop cplg., comp;
 1" x 1" Fig. 413 Tap reamed

NOTE: 1" service located 63.0 ft. W x W line Avon St.

[illegible]

APPLICATION No.: 26877

TAP CLEARED

LOCATION: N.S. 117 Rockdale Ave., W x Hemlock St.

OWNER: Nu Way Car Wash

MEASURES: 1" Copper 3-3-65
E from W line Avon 3.1 ft.
S from N line Rockdale Ave. 3.8 ft.
E from W line Building 12.1 ft.
S from Meter Box 9.9 ft.
Main is 64 ft. S x N line.

Oct. 11, 1994 Owner called requesting permission to fill in meter pit.
Very dangerous situation in parking lot. Checked by M. Rose found to be meter pit for
this service. Was shut off since approx. 1970 - Cement lined main - this service is plugged at main.
This service cannot be reactivated.

INACTIVE
SERVICE

DATE

BEF.

AFT.

REMARKS

[illegible]

CHARGE OUTS

[illegible]