

APPLICATION No.: 23563

TAP CLEARED ✓

LOCATION: W.S. Walker St., M x MaldenOWNER: N.B. Housing Authority

MEASURES: 4" op per Nov. 27.1951

1-4" Gatebox 220#; 1-4" Dar. Gate Valve

S from S Hathaway Rd. 196.1 ft.

E from W Walker 16.0 ft.

N from S Bldg. 5.1 ft.

Jan. 3, 1985 Repaired 4" break with a 4" Smith blair #227 repair sleeve.

Location: W x W line Walker St. 20 ft.  
S x S line house 16 ft.

Feb. 23, 1987 Repaired 4" break with a 4" Smith Blair #227 clamp cplg:

Location W x W line Bldg. 37 22.0 ft.

W x service gate 89.0 ft.

4" main S x curb 4.0 ft.

NOTE: C.I. main going up lane - not copper!!

Nov. 16, 1990 Repaired crack in C.I. main inside service drive  
W x Walker St. Location: 11.0 ft. E x W line house #37

1 - 4" Smith Blair #226 Clamp cplg. 7 1/2" W. Main 20.0 ft. S x S line house #37

Housing Authority will take care of cut - inside Private Way

See main pipe book for other breaks

4-17-2000 Repaired 1 1/2" service broken by Waste Water @ a point  
3 ft. W x Bldg. #89 to a point 5 ft W x #89. Stock: 2 ft. - 1 1/2"  
Copper tubing, 2 - 1 1/2"x1 1/2" cop to cop cplg.. comp.

[illegible]

## This image shows a blank, aged, cream-colored page, likely an endpaper or flyleaf of a book. The paper has a slightly textured appearance with some faint smudges and discoloration, characteristic of old paper. The left edge of the page shows the binding structure, including what appears to be stitching or staples. There is no text or other markings on the page.