OWNER: City of New Bedford School  W from W line N from S line  Nemasket  Ne	TAP CLEARED /				
MEASURES: 1-4" Gate Valve all bell 1-4" C.I. Gatebox 220# W from W line N from S line Nemasket Nemaske	DATE BEF. AFT. REMARKS				
W from W line N from S line  Nemasket  Nemaske					
W from W line N from S line  Nemasket  Nemasket  11.8 ft.  Sept. 18, 1995 Replaced all asbestos pipe with 4" ductile or CICL pipe by cutting old gate & 6" pc. of 6" CI pipe off tee in street.  Installed new 4" Darling Gate on existing 1.5 ft. pc. left on tee and approx. 65 ft4" ductile to 4" Smith Blair cplg. installed by previous repair work.  Cplg. is located S x S line Nemasket St. 54.0 ft.  Note: All asbestos pipe has now been removed on this service between this repair & eaelier repair - according to Tony Braz, Supt. Maint. School Dept.  St. cut - by School Dept.					
Sept. 18, 1995 Replaced all asbestos pipe with 4" ductile or CICL pipe by cutting old gate & 6" pc. of 6" CI pipe off tee in street.  Installed new 4" Darling Gate on existing 1.5 ft. pc. left on tee and approx. 65 ft4" ductile to 4" Smith Blair cplg. installed by previous repair work.  Cplg. is located S x S line Nemasket St. 54.0 ft.  Note: All asbestos pipe has now been removed on this service between this repair & eaelier repair - according to Tony Braz, Supt. Maint. School Dept.  St. cut - by School Dept.					
6" CI pipe off tee in street. Installed new 4" Darling Gate on existing 1.5 ft. pc. left on tee and approx. 65 ft4" ductile to 4" Smith Blair cplg. installed by previous repair work. Cplg. is located S x S line Nemasket St. 54.0 ft. Note: All asbestos pipe has now been removed on this service between this repair & eaelier repair - according to Tony Braz, Supt. Maint. School Dept. St. cut - by School Dept.					
Installed new 4" Darling Gate on existing 1.5 ft. pc. left on tee and approx. 65 ft4" ductile to 4" Smith Blair cplg. installed by previous repair work.  Cplg. is located S x S line Nemasket St. 54.0 ft.  Note: All asbestos pipe has now been removed on this service between this repair & eaelier repair - according to Tony Braz, Supt. Maint. School Dept.  St. cut - by School Dept.	e by cutting old gate & 6" pc. of				
Note: All asbestos pipe has now been removed on this service between this repair & eaelier repair - according to Tony Braz, Supt. Maint. School Dept.  St. cut - by School Dept.	approx. 65 ft4" ductile to				
	this repair & eaelier repair -				
Excavation by filton - Fifting by Netson cardosa					

METE	RH	IST	ORY					CHARGE OUTS
DATE	SET	SIZE	MAKE	NUMBER	READING	TEST	REMARKS	
7-28-56		411	Pitts Empir	e 9817058				
		100						
		1000						
				*				
				1				