

APPLICATION No.: 5167

TAP CLEARED

?

LOCATION: 504 So. Second St.

OWNER: Joseph Simas

MEASURES:

 $\frac{1}{2}$ "

H lead

Dec. 15, 1885

S from

Balckmer St.

161.2 ft.

W from E line Second St.

6.6 ft.

S from N line house

10.2 ft.

12/19/77: Renewed 6" outside curb stop to property line.  $6\frac{1}{2}$  ft. -  $\frac{3}{4}$ " copper;  $\frac{3}{4}$ " curb stop; 2- $\frac{5}{8}$ " x  $\frac{3}{4}$ " lead to cop. adapt. XXS; Caldwell stop box;

2/23/94 Wayne Richmond while reading meter noticed leak before meter. Muriel to notify owner in writing to repair leak.

10/19/95 Gil Souto reported leak under foundation. Owner refuses to fix. Memo sent to Muriel - to sent registered letter.

11/25/97: Renewed from main to ins. cellar (8 ft. ins. prop. line)

Stock: 35.0 ft.  $\frac{3}{4}$ " copper tubing, 1-  $\frac{3}{4}$ " curb stop, 1-#1

Caldwell stop box, 1- 1/2x3/4 Fig. 413.

=====

DATE

BEF.

AFT.

REMARKS

11/25/97

974801561

Clean Elect.

11/25/97

tap reamed

[illegible]

## CHARGE OUTS

[illegible]

APPLICATION No.: 18081 C

TAP CLEARED

LOCATION: So. Second E.S., S. of Blackmer

OWNER:

MEASURES: 5/8"

Conn of 5167 Conn made By taker.

DATE \_\_\_\_\_

BEF.

AFT.

REMARKS



[illegible]

## CHARGE OUTS

[illegible]