

APPLICATION No.: 6568

TAP CLEARED ✓

LOCATION: 99 FRUIT ST

DATE

BEF.

AFT.

REMARKS

OWNER: ANTONIO R DESOUZA

8/21/95: TAP REAMED

31-313

MEASURES: 5/8" H Lead Sept.2,1890

E from MULBERRY ST 91.5 ft

S from N Line FRUIT ST 6.0 ft

E from W Line HOUSE 9.2 ft

Aug 21,1995:

Renewed from main to ins.cellar ( 9ft ins.prop line)

Stock: 36 ft 3/4" copper tubing 1-3/4" curb stop

1- Caldwell stop box 1-3/4x5/8 Fig 413

=====

[illegible]

## CHARGE OUTS

[illegible]



APPLICATION No.: 6568

TAP CLEARED 8821-1425

LOCATION: 99 Fruit St.

OWNER: Antonio R. De Souza

MEASURES: 5/8" H lead Sept. 2, 1890

E from Mulberry St. 91.5 ft.

S from N line Fruit St. 6.0 ft.

E from W line house 9.2 ft.

5/25/88: Renewed from main to a point lft. Stock: lft 3/4"  
copper tubing 1 - 3/4x5/8 lead to cop adapt. xxs

1 - 3/4" corporation tap \_\_\_\_\_ 1-6" x 3/4" service saddle

7/19 Dirty Water Flow test Howland mill

7/25 D.W. shutdown for 36 Larch St. Sample was  
a little hazy 2:40 PM Deaats Gave Rust Remover.

8/21/89 D. W. fir Dept meet by plane Bolton St + Sagamore St.  
D. P. W Thompson St + Lombard St Truck 24 8/21/89

Toilet Running 10-24-94 Augusto

BRADBURY-WARING, INC.

[illegible]

# CHARGE OUTS