

APPLICATION No.: 8424

## TAP CLEARED

LOCATION: 63 Crapo St

OWNER: \_\_\_\_\_

31-313

MEASURES: 05/15/2019

Lead service line replacement program

Phase 1, Contractor P Gioioso &amp; SOn

Type CU, Diameter (in) 1, Water pressure 100

Distance from main to curb stop (ft) n/a

Distance curb stop to meter (ft) 18

Distance from curb face to curb stop (ft) 1.5

Depth of service (ft) 4

Total length of new pipe installed (ft) 18

Curb stop replaced: no

Corporation replaced: no

Ball valve furnished: yes size 1"

DATE

BEF.

AFT.

REMARKS

DATE	SET OUT	SIZE	MAKE	NUMBER	READING	TEST			REMARKS

APPLICATION No.: 8424

LOCATION: 63 Crapo St.

OWNER: Wm. H. Tillson & N.B. Howard

MEASURES:  $\frac{1}{2}$ " H lead Nov. 27, 1895

S from Thompson St. 15.1 ft.

E from W line      Crapo St.      6.8 ft.

N from S line house 8.5 ft.

Dec. 27, 1976 Renewed from 6" outside curb stop to a point 3 ft. inside curb stop.

3½ ft. - 3/4" Copper tubing  
2 wipe joints

3/2/94 broken hydrant - 61-3 Crapo St. (Morro) cellar flooded 4-5 ft. water in cellar - M. Rose III

June 30, 1995: During cement lining Biszko Cont. renewed from main to a point lft in front of main

Stock: 1ft 3/4" copper tubing 1-3/4x5/8 lead-cop adapt.xxs  
1- 3/4 x 5/8 Fig 413 All stock supplied by contractor

July 18, 1995: Crapo St. reconstruction

Todesco Corp renewed service from main to prop line  
Cont. supplied all stock & will maintain trench.

Stock: 18ft 3/4" copper tubing 1-3/4" curb stop  
1-stop box 1-3/4x5/8 lead-cop adapt.xs 1-3/4x5/8 Fig 413

Inspt.Dennis M0nty

ADDITIONAL MEASURES: S x N line house 12.6 ft  
N x S line house 21.6 ft

TAP CLEARED

DATE \_\_\_\_\_

BEF.

AFT.

REMARKS

6/30/95: tap reamed

7/18/95: tap reamed



[illegible]

## CHARGE OUTS

[illegible]