

Storm

Permit: SMP-23-37

Address: 46 Union St

Enters: Union St

Sewer Plot: 69

Plot/Lot: 47/240

From Property of: MDBC Realty LLC

20

ROSE ALY

- NBGIS.DBO.sCleanOut
- NBGIS.DBO.sCleanOut
- NBGIS.DBO.CommonManholes

NBGIS.DBO.sCleanOut

Cleanout Type

- Cleanout
- Flushing Structure
- Other

DBO.CBs_2023

CBTYPE

- Bradley Head
- Frame & Grate with inlet
- Frame & Grate no inlet
- Frame & Grate
- Other
- Not found
- No access

NBGIS.DBO.sGravityMain


Water Type

- Combined Waste Water
- Combined Sewer Overflow
- Sewage
- Storm Runoff
- NBGIS.DBO.swGravityMain
- NBGIS.DBO.sLateralLine
- NBGIS.DBO.Interceptor
- NBGIS.DBO.sPressurizedMain

Infiltration

Type

- Detention Pond
- Oil Separator
- Other
- Recharge



Spatial Reference

Name: NAD 1983 StatePlane Massachusetts Mainland FIPS 2001 Feet

PCS: NAD 1983 StatePlane Massachusetts Mainland FIPS 2001 Feet

GCS: GCS North American 1983

Datum: North American 1983

Antonio.Lemos@newbedford-ma.gov
September 2023