CONCRETE LOCATION — EAST SIDE OF EIGHTH ST. JULY 14, '15
OFF NORTH SIDE OF UNION ST.
SANBORN'S

Mary E. MacKelvey

Frank W. Hawkins

Fredk. M. Ashley

50.85 42.7 72.05

EIGHTH ST.

EAST CURB

WEST CURB

UNION ST.

TAUNT. SEPT. 23, '15
WM. B. SMITH, C.E.
JOHN E. LEWIS, JR.

SOUTH CURBING OF

SCHOOL ST.

SIDE WALK

Francis and
Horatio Hathaway Dev.

53.2

29.0

50. ST. LINE
STA. 2+26.89

#75

#76

7.55

3.55

3.15

13.7

8.8

4.95

4.0

2.8

1.2

2.25

1.8

TAR WALK.

UP

STA. 2+20

STA. 2+10

STA. 2+0

STA. 1+90

STA. 1+80

STA. 1+70

STA. 1+60

STA. 1+52.89

SEE Pages TAR WALK 85, 86.

HAS

ST. WALL BUILDING

TAR WALK

ZERO MINUS 5' EAST.

0-5' Line

0-9.93 Line

W. FACE

CONCRETE

RETAINING WALL.

28.8

45.0

SCHOOL ST. (CONCRETE) DRIVEWAY TO N.B. GAS & EDISON LIGHT CO'S ELECTRIC GARAGE

CONCRETE

N.B. GAS & EDISON LIGHT Co.

#73

SEE LEVEL NOTES ON PAGES 129 and 130.