1+52.89
5-8
1+58.69

STA.	B.S.	H.I.	F.S.	E.L.
	1.675	101.675		100.0
0-10.93 EAST			7.775	93.9
1+52.89				
0-17.09 EAST			7.777	93.898
1+				
0-24.60			7.783	93.892
1+52.89				
0-10.93			7.867	93.808
1+58.69				
CATCH BASIN 0-21.43			7.963	93.712
1+38.56				
			7.90	93.775
			5.468	96.207
0-10.93 CONCRETE DRIVE			7.648	94.027
1+70				
0-19.93 D.		D.	7.653	94.022
1+70				
	2.81	99.017		96.207
TRAP			5.055	93.962
0-17.09 East.)			5.065	93.952
1+57.50			5.260	93.757
			5.155	93.862
			5.274	93.743
			5.05	93.967
			4.912	94.105
			9.01	90.007

SEE SKETCH ON PAGE 108

ELECTRIC GARAGE

SAT. SEPT. 11, 1915 126

Wm. B. Smith, Jr.
John E. Lemos, Jr.

The Sun almost blinding — Very Hot.

South East Corner of Bottom Stone Step Rear 468 Pleasant St.
SURFACE CONCRETE AT NORTH WEST COR. of DRIVEWAY TO GARAGE
" " at Centre of DOOR-SCHOOL ST. " " "
" " " N.E. CORNER " " " " "
" " " Ft. W. Retaining Wall " " " " "
TOP (CIR.) GRATING C.B. SCHOOL ST. " " " " "
SURFACE CONCRETE AT NE. COR. So. Retng Wall " " " "
TOP " " " So. E Cor. Sa. RETAINING WALL of GARAGE The So. W. COR. " "
SURFACE CONCRETE Ft. West Retaining WALL-SCHOOL ST. " " "
" " " Ft. EAST " " " " " "
TOP SURFACE CONCRETE RETAINING WALL-AT So. West Cor. GARAGE
TOP OF IRON PLATE OF TRAP #1 NEAR School Entr. of Garage
SURFACE OF Con. at Ctr. of Door Way - Inside Wall Line - SCHOOL ST. DRIVEWAY GARAGE
TOP OF IRON GRATING OF CATCH BASIN #4 IN GARAGE Below PIPE SHOP
TOP OF IRON PLATE OF TRAP #2 About the Ctr. of Garage
TOP OF IRON GRATING OF CATCH BASIN #5 IN GARAGE.
TOP OF IRON GRATING OF TRAP #3 IN GARAGE West of OFFICE
SURFACE OF CONCRETE IN GARAGE AT Repair PIT
" " " at Bottom of " "