

Sometime between 1911 and 1953, Chapman hydrant was replaced with 4" Darling;

In 1953, Darling hydrant was removed and Chapman hydrant set at this location.

In 1966. Chapman had

In 1966, Chapman hydrant was replaced and relocated easterly because of a Service Station.