

SERVICE PIPE RETURN.

No. 5733

No. 155
For Henry Tancier No. 5. Howard Street.
no. 47 Cedar Grove St.

<u>7.5</u>	lineal feet of earth excavated at	<u>23</u> cents per foot,	.	.			173
	lineal feet of rock excavated at		cents per foot,	.	.		
<u>9.0</u>	lineal feet of $\frac{1}{2}^H$ inch lead pipe at	<u>18</u> cents per foot,	.	.			162
	lineal feet of inch iron pipe at		cents per foot,	.	.		
	lineal feet of inch tin lined pipe at		cents per foot,	.			
						Lapping	200
Proportion of other expenses for putting services into premises,						.	.
Amount,						.	\$
							535

Dec. 13th 1887.

R. L. P. Biggeshall Superintendent.

WATER REGISTRAR'S OFFICE. *70*

Dec. 12th 1889.

Please put in a Service upon the premises described above, and make return of the expense of the same to this office.

J. H. Hathaway Water Registrar.

Water Registrar.

5733

Henry Harcier
Howard Street