1 Farm
27
1mc
1 bJ
Hose

New Bedford Water Works.

SERVICE PIPE RETURN.

For Henry P. Jenney No. Belle Roa	el a	2.1.7
For Verry O. Jenney No. Belle ava	d	treet.
The expense for labor and materials to be paid		
15-14 by the applicant is as follows:		
lineal feet of earth excavated at cents per foot,		
lineal feet of rock excavated at cents per foot,		
1.00 lineal feet of $\sqrt[3]{y}$ inch lead pipe at $2/$ cents per foot,	21	
lineal feet of inch iron pipe at cents per foot,		
lineal feet of inch tin lined pipe at cents per foot,		
labor 11 00 1 lb. solder 15	11	13.
Proportion of other expenses for patting services into marriage		
Proportion of other expenses for putting services into premises,	2/_	
Proportion of other expenses for putting services into premises,	34	15
Amount,	34	15
Amount,	3 4	13 ⁻ -
Amount, Office of Superintendent, R. B. P. boggerhard Su	3 4 perinten	13 - 1896. edent.
Amount,	3 4 3 perinten	13 - 1896. edent.
Amount, Office of Superintendent, B. B. P. boggerhand Su WATER REGISTRAR'S OFFICE. May	perinten	13- 1896. Edent.
Amount, Office of Superintendent, R. B. P. bogonna Su WATER REGISTRAR'S OFFICE. May To the Superintendent of the New Bedford Water Works.	perinten	dent. 189 (2
Amount, Office of Superintendent, R. B. P. bogoshaw Su WATER REGISTRAR'S OFFICE. May To the Superintendent of the New Bedford Water Works. Please put in a Service upon the premises described above, and	perinten	dent. 189 (2
Amount, Office of Superintendent, R. B. P. bogonna Su WATER REGISTRAR'S OFFICE. May To the Superintendent of the New Bedford Water Works.	perinten ' make r	edent. 189 (2 eturn

8560 Henry P. Jenney Wride acu are or of Belle. Rd.