Make	Smith M.J.								
Size	611			Set 2/21/75			Box iron		
On	line of								Si
S	from	S	line	No	rth		St.	17.0	f
W	from	W	line	Pleasant		St.	42.0	f	
E	ctr		Hydrant			13.0			