

STOP GATE-4" and upward				HG-1224		Hydrant	
Pleasant				St.	S	Side	Weld
Make							
Size				Set		Box	
On		line of				St.	
S	from	S	line	Weld		St.	5.0
E	from	W	line	Pleasant		St.	5.0
N		ctr.		Hydrant			8.0
OPEN TO THE RIGHT							