

Sept. 9,1953, ser. leak, renewed from curb stop to inside. Tap reamed. Used 12% of 3/4" cop. tubing type k. I wiped joint. Bill No. 47863.