
		APPLICATION No.: 10262 3/4"			TAP CLEARED					
	LOCATION:	472 Cottage St.			DATE	BEF.	AFT.	REMARKS		
		Russell D. Smith			1/29/02	745	am	2002-480-0414		
	MEASURES:		OCT. 22,	1902						
	MEASURES:	3/4" N from	Willis	116.5 ft.						
		W from E line	Cottage	7.0 ft.						
		S from N line	House	5.4 ft.						
	Dec. 12, 195	O Repaired leak at t	ap							
	1 ft. of 3/4	" copper tubing	1" I.P. Fem. x 3/4 cop.							
				fig. 413						
	July 16, 1969 Renewed from a point 6" outside of the curb stop to									
	the property line. 7½ ft. 3/4" copper tubing 3/4" Hays curb stop 1 - wiped joint				3					
	7 1 111/3 04	10 500p	T - MIDAG JOING							
D	ecember 11,	2002: Renewed from m								
		; 1 - 3/4" curb stop;	4							
	ig. 413; tap	ream _{ed}								
	7/15/16 spot repair at proprty ling						(
	4 ft	3/4" copper tubing								
	1 ft			\						
	1 ft	5/8" lead to coppe 3/4 copper copper	DPI							
	lead	worker: Manuel Alve	DP1							
1										
M.										



CONNER: 31-313 MEASURES: 3/17/2020: LEAD Service Line Replacement Program Phase 1 TYPE:COPPER Diameter1 inch: Water Pressure PSI Distance from main to curl stop (ft) 22.3 Distance curl stop to meter (ft) 16 Distance from curl face to curl stop 1.8 Depth of service(ft) 4.0 Total Length of new pipe installed (ft) 27.8 Curl stop replaced Yes; Size linch Corporation replaced YES; Size linch Ball Valve replaced NO; size 0.75 inch	175	472 Cottage APLICATION No.:	TAP CLEARED				
MEASURES: 3/17/2020: LEAD Service Line Replacement Program Phase 1 TYPE:COPPER Diameter1 inch: Water Pressure PSI Distance from main to curl stop (ft) 22.3 Distance curl stop to meter (ft) 16 Distance from curl face to curl stop 1.8 Depth of service(ft) 4.0 Total Length of new pipe installed (ft) 27.8 Curl stop replaced Yes; Size linch Corporation replaced YES: Size linch	LOCATION:		DATE	BEF.	AFT.	REMARKS	
MEASURES: 3/17/2020: LEAD Service Line Replacement Program Phase 1 TYPE:COPPER Diameter1 inch: Water Pressure PSI 50 Distance from main to curl stop (ft) 22.3 Distance curl stop to meter (ft) 16 Distance from curl face to curl stop 1.8 Depth of service(ft) 4.0 Total Length of new pipe installed (ft) 27.8 Curl stop replaced Yes; Size linch Corporation replaced YES: Size linch							
TYPE:COPPER Diameter1 inch: Water Pressure PSI 50 Distance from main to curl stop (ft) 22.3 Distance curl stop to meter (ft) 16 Distance from curl face to curl stop 1.8 Depth of service(ft) 4.0 Total Length of new pipe installed (ft) 27.8 Curl stop replaced Yes; Size linch Corporation replaced YES: Size linch							
Distance from main to curl stop (ft) 22.3 Distance curl stop to meter (ft) 16 Distance from curl face to curl stop 1.8 Depth of service(ft) 4.0 Total Length of new pipe installed (ft) 27.8 Curl stop replaced Yes; Size linch Corporation replaced YES; Size linch		3/17/2020: LEAD Service Line Replacement Progra Phase 1	m				
Distance curl stop to meter (ft) 16 Distance from curl face to curl stop 1.8 Depth of service(ft) 4.0 Total Length of new pipe installed (ft) 27.8 Curl stop replaced Yes; Size linch Corporation replaced YES: Size linch		TYPE:COPPER Diameter1 inch: Water Pressure PSI	50				
Distance curl stop to meter (ft) 16 Distance from curl face to curl stop 1.8 Depth of service(ft) 4.0 Total Length of new pipe installed (ft) 27.8 Curl stop replaced Yes; Size linch Corporation replaced YES: Size linch		Distance from main to curl stop (ft) 22.3 Distance curl stop to meter (ft) 16 Distance from curl face to curl stop 1.8 Depth of service(ft) 4.0					
Depth of service(ft) 4.0 Total Length of new pipe installed (ft) 27.8 Curl stop replaced Yes; Size linch Corporation replaced YES: Size linch							
Curl stop replaced Yes; Size linch Corporation replaced YES; Size linch							
Corporation replaced YES: Size linch							
Corporation replaced YES: Size linch		Curl stop replaced Yes; Size linch					
Tarve repraced No, Size 0.75 inch		Corporation replaced YES: Size linch					
		size 0.75 inch					

