

APPLICATION No.: 12332

TAP CLEARED

LOCATION: 482 Bolton St.

DATE

BEF.

AFT.

REMARKS

OWNER: Mrs. Mary Cambra

MEASURES: 5/8"

~~H lead~~ COPPER Sept. 22, 1908

N from

Thompson St. 130.0 ft.

W from E line

Bolton St. 8.3 ft.

S from N line

house 10.4 ft.

August 20, 1971 Renewed from $\frac{1}{2}$ ft. outside curb stop to inside cellar.
 20 ft. - $\frac{3}{4}$ " Copper tubing $\frac{3}{4}$ " Hays curb stop
 1 wipe joint Buffalo Stop Box

- - -

10.16.2013 - Lead Service Line Replacement Program

Contactor: P. Gioioso and Sons

Type: CU, Diameter (in) 1, Water Pressure (PSI) 100

Distance from main to curb stop (ft) 25.2, Distance curb
 stop to meter (ft) 16, Distance from curb face to curb
 stop (ft) 1.5, Depth of service (ft) 4.0, Total length
 of new pipe installed ft 25.2

Curb stop replaced: Yes, Size 1"

Corporation replaced: Yes, Size 1"

Ball Valve Furnished : No, Size $\frac{3}{4}$ "Remarks: $\frac{3}{4}$ -1" union installed 1.0 LF outside curb stop

CHARGE OUTS

[illegible]