


Sept. 1978 discontinued, plugged at main while cement lining. Material abandoned in ground.



2/2/67, renewed from 1 ft. outside curb stop to 2 ft. inside curb stop; 3 ft. 3/4" copper tubing used; 1 3/4" curb stop.

Sept 1978 discontinued, plugged at main while cement lining. Material abandoned in ground.