

APPLICATION No.: 13096

LOCATION: 157 - 159 Hathaway St

TAP CLEARED

OWNER:

31-313

MEASURES:

1" Copper Service

06/27/2018 Lead Service Line Replacement Program

Phase 1, Contractor P Gioioso & Son

Type CU, Diameter 1in, Water pressure 70

Distance from main to curb stop (ft) N/A

Distance from curb stop to meter (ft) 16.5

15.5 ft to house + 1 ft wall

Distance from curb face to curb stop (ft) 1.0

Depth of service (ft) 3.5

Total length of new pipe installed (ft) 19.5

16.5 ft + 3 ft whip

Curb stop replaced: no

Corporation replaced: no


Ball valve furnished: yes size 1"

DATE

BEF.

AFT.

REMARKS

[illegible]

APPLICATION No.: **13096**

TAP CLEARED

LOCATION: 157-159 Hathaway

OWNER: A Freitas

MEASURES: E from Brook St. 257.2 ft.
S from N line Hathaway St. 9.0 ft.
E from W line house 12.4 ft.

May 7, 1952 Leak at curb stop repaired
6" of 3/4" copper tubing oneach side of curb stop
3/4" Copper Stop, fig. 415

Feb. 11, 1976 Renewed from 6" outside curb stop to 3 ft.
inside curb stop.

3 ft. - 3/4" Copper tubing Caldwell Stop Box
5/8" x 3/4" lead to copper adaptor XS

2005 earle st sewer project 3/4 copper main-prop line

[illegible]

CHARGE OUTS

[illegible]