

Jan.26,1915 the use of this service for Rear 1527 Acush. Av. discontinued; 34 ft. of it from the house east now becomes 16070C, a connection. of Ser.6809.

Sept. 1978 discontinued, plugged at main while cement lining. Material abandoned in ground.

