

LOCATION: 352 Arnold St.OWNER: Harold Robins

DATE

BEF.

AFT.

REMARKS

3/9/65Reamed

MEASURES:

5/8"L leadAug. 16, 1915E fromArmour (north)22.9 ft.N from S lineArnold6.8 ft.E from W lineHouse4.2 ft.

March 9, 1965 Renewed service from main to property line.

14½ ft. - 3/4" copper tubing; 1-3/4" cop to cop stop,fig. 415; 1 - 5/8" reused corp. cplg.; 1 lb. wiping solder.

Tap Reamed

*mrs. Souza 9935662**Complacence of poor pressure check out by**Bento O.R. 2/25/91*

METER HISTORY

CHARGE OUTS

[illegible]