APPLICATION No.: 205 74	TAP CLEARED 8505-04/76			
LOCATION: 53 Mary W.S., S. of Tarkiln Hill Rd.	DATE	BEF.	AFT.	REMARKS
OWNER: N.B. 5¢ Savings Bank				
MEASURES: 5/8"	10/24/18	2		2012-4211457
S ffom Tarkiln Hill Rd. 265.8 ft E from W line Mary 9.0 ft				
N from S line House 11.9 ft				
2/12/85: Renewed from lft. outside curb stop to prop				
line.(done so curb box could be set on southside of both sewer & drain which run high) Stock: 9.0ft. 3/4" copper				
tubing 1 3/4" curb stop 1 Caldwell stop box				
2 3/4x5/8 lead to cop adapt.xs.NOTE: inside adapter well under cement wall in owners property and is under				
both sewer & drain. Old lead in concrete at this point.				
10 20 10 1 1 1 1 1 1				
10-30-12 - leak inside private property				
11/3/12 - Mike Bergeron repaired leak inside private				
property on private time for a friend.				

	一等			
r	3			• • •
	3			

METE	RH	ISTO	DRY					CHARGE OUTS
DATE	SET	SIZE	MAKE	NUMBER.	READING	 TEST	REMARKS	
5-9-33	1		Empire A X	1649165				
	1.3	11.4						
						,		
-				e .				