

APPLICATION No.: 21774

TAP CLEARED

LOCATION: 1080 E.S.Rd.Fr. Blvd.(E)n. of Rd. Fr. Blvd. S.

OWNER: Daul e. Bauer

MEASURES:

2" Copper May 16, 1939
2" Darl. Gate Box Iron Box (Hurricane Damage)

N from N line Rd. Fr. Blvd. (S) 186.5
W from E line Rd. Fr. Blvd. (E) 51.2
S from N line Bldg. Pavilion 80.4

Laid with drain -79'-2" Copper

May 26, 1966 Removed 2" tapping gate valve & 8" x 2" tapping sleeve
from East Rodney Fr. Blvd. main - Service #21774-2".

1 8" Smith Blair Repair Sleeve style 222

9.05-9.15 was installed at the above location.

Measures of Location of Smith Blair Repair Sleeve:

S x S line Seymour St. 60.8

E x W line E. Rod. Fr. Blvd. 14.0

NOT READING 8/27/2009

DATE

BEF.

AFT.

REMARKS

[illegible]

CHARGE OUTS

[illegible]