APPLICATION No.: 27754 4" CL.C.I	TAP CLEARED			
LOCATION: S.E. Cor. 60 Brigham & Tabor St.	DATE	BEF.	AFT.	REMARKS
OWNER: DR. Gredman - HEDICAL ARTS BLDG. of				92304/15
MEASURES: 4" C.L.C.I. August 12m 1968 N from S line Taber 18.4 ft.				clean E lect.
E from E line Brigham 20.5 ft.				962/00705
Main is 18.4 ft. N x S line Taber st. Jan. 21, 1977 Owners plumber - Cormier Plumbing -				
repaired leak at the prop. line.				
1 - 4" Smith Blair Style 227 Repair cplg.				
December 8, 1992 Repaired crack around 4" cast iron service at a point 6" outside property line.				
1 - 4" Smith Blair #226 single band clamp 7½" W				
May 20, 1996 Renewed from the 4" gate valve to a point 5 ft. S x	gate va	ilve:		
1 fft 4" ductile pipe 1 - 4" 1/4 Bend, mech.				
1.3 ft 4" ductile pipe 1 - 4" 1/4 Bend, mech.				
2.7 ft 4" ductile pipe				
1 - 4" Ford cast cplg N x S line Taber St. 9.5 ft.				

METE	R H	ISTO	DRY			45		T Sal	6-11-1	CHARGE OUTS
DATE	SET	SIZE	MAKE	NUMBER	READING		TEST		REMARKS	
				- 2	- A		V.			
						10.00	19			
					Lines		,			
					10 1 F		8-11			
						- 1				
		1					-			
							57/			
					- The state of the					Carlo
-										
							× ,			
						7				
-										
-										
						ie in in				
										In the second se
					7					
		3					4			