

55 Sam'l Barnett Blvd.

APPLICATION No.: 28641

## TAP CLEARED

LOCATION: N.S. Road "B", W. x Industrial Pk. Rd.

OWNER: American Flexible Conduit Co.

MEASURES: July 27, 28, 31, Aug. 1, 1972

4"

W from 1st hyd. W x Railroad track 60.0 ft.

S x N line Road B 70.5 ft.

W from W Bldg. 130.0 ft.

S from SW. cor of Bldg. 120.0 ft.

Main is 72 ft. S x N line.

Jan. 20, 1998 Gioioso Const. while excavating under main, caused leak.

Repaired by installing a 4" Smith Blair #227 Double band clamp cplg. 4.74-5.57 OD 7 1/2" W  
----- Repair Sleeve is 10.2 ft. N x 4" gate valve.Jan. 19, 2000 Repaired leak by installing a 4" Smith Blair #226 Single Band Clamp 7 1/2" W.  
at a point 8 ft. N x gate.

Note: flowable fill was installed on Jan. 21, 2000.

[illegible]

## CHARGE OUTS

[illegible]

APPLICATION No.: 28642

## TAP CLEARED

LOCATION: N.S. Road "B"; W x Industrial Park Rd.

DATE \_\_\_\_\_

BEF.

AFT.

REMARKS

OWNER: American Flexible Conduit Co., Inc.

MEASURES: 8" C.I.C.L. July 12, 13, 14, 1972

1st. hyd. W x	Railroad tracks on	
	B Street	66.4 ft.
S x N line	B Street	74.5 ft.
E x E "	Building	188.0 ft.

Main is 72 ft. S x N line.

F S  
I U  
R P  
E P  
L  
Y

May 13, 1999	Repaired leaking #441 cplg. This service possibly damaged by Gioioso Cont. while digging under on Jan. 98 installing drain.		
	Cut out & removed a 8" Smith Blair #441 cplg which was leaking.		
	Installed a 8" 22° Bend, 12" pc. of 8" ductile pipe and an 8" Rockwell #441 cplg.		



[illegible]

5-13-99

ND