

75

chur L

Body

Nov. 2

1 ft.

[illegible]

[illegible]

OWNER:  
31-313

31-313

6" Ductile Iron Fire Supply

5/7/10 - Emerald Excavating connected to existing stub  
at property line & installed new fire supply service to  
building - Reducer 8" - 6" - 3.5 ft inside property  
line - owner charged \$ 70 Inspection fee  
Inspected by Percy Reynolds

-----

28761

TAP CLEARED

DATE \_\_\_\_\_

BEE.

AFT.

REMARKS



[illegible]

75 mae Arthon

