# 16 APPLICATION No.: 29162	- Share	TAP	CLEAR	ED /
LOCATION. E.S. Hassey St. S x South St.	DATE	BEF.	AFT.	REMARKS
OWNER: Sea View Fillet Co. Rfc- Seadow	11/3/97	7		974500371
MEASURES: 8" C.I. 1974				
S x S line South St. 251.0 ft.				
W x E line Hassey St. 46.0 ft. N x S line Meter Pit 3.0 ft. W x W line Bldg. to meter pit 291.0 ft.	*			
Main is 47 ft. W x E line.				
Nov. 3, 1997 Repaired leak on 8" fire supply. While contra	tor rela	cated	meter	pit inside
property - caused leak in sidewalk. This service is 8" from 3" reduced at property line. Leak occured on last 5 ft. of 8	the main before	to the	prope tv lir	rty line with
Installed 2 - 8" Pipe clamps with 3/4" threaded rods from bell property line.	l (5 ft.	W X E	line)	to the
2 - 8" Pipe clamps w/ 3/4" threaded rods				
Note: Meter pit relocated on extension of new addition of Fish Pla	nt. New	2" co	pper l	ine was
installed along side of SS Bldg.				
		1	1	

METER HISTORY									CHARGE OUTS							
DATE	SET	SIZE	MAKE	NUMBER	READING	TEST		TEST		TEST		TEST	TEST		REMARKS	
	OUT								THE PARTY OF THE P							
						-										
									-							
								-								
					,											
	20															
		-														
					,											