

6095

TAP CLEARED

LOCATION:

OWNER:

31-313

MEASURES:	N X Rivet St	85.3 ft
	W X E Line First	6.5 ft
	S X N Line Bldg	14.0 ft

1" Copper Service

12/12/2018 Lead Service Replacement Program

Phase 1, Contractor P Gioioso & Son

Type CU, Diameter 1in, Water pressure 95(meter)

Distance from main to curb stop (ft) N/A

Distance from curb stop to meter (ft) 13.5

Distance from curb face to curb stop(ft) 1.5

Depth of service (ft) 4

Total length of new pipe installed (Ft) 13.5

Curb stop replaced: NO Corporation replaced: NO

Ball valve replaced: Yes size 1"

DATE _____

BEF.

AFT.


REMARKS

3/10/81 Ream

6/7/84 Ream

[illegible]

lies:



6095

APPLICATION No.:

TAP CLEARED C 1808

LOCATION: 588-90 So. First

OWNER: Jos Bourasse

MEASURES: $\frac{1}{2}$ "

N from	Rivet	85.3
W from E line	First	6.5
S from N line	Bldg.	14.0

Dec. 30, 1974 Renewed from 6" outside curb stop to property line.

7 ft. - 3/4" Copper tubing
2 - 5/8" x 3/4" lead to cop.
adaptor Xs

1 - 3/4" Curb Stop
Caldwell Stop Box

MAR 10 1981 adaptor Xs

Renewed from main to 1.5 ft. from main. 1.5 ft.-3/4" copper; 5/8" x 3/4" Fig. 413; 5/8" x 3/4" lead-cop. adapt. XS

May 17, 1984 - Renewed from 7 Ft. outside of curb stop
to a point 9 Ft. outside curb stop;
2.0 Ft. - 3/4" copper tubing; 1 - 3/4" curb stop;
2 - 5/8" x 3/4" lead to copper adaptors XS
(Service damaged by Gas Co. while digging trench in St.)

June 7, 1984 - J.F. Kennedy Hwy. Proj.

Dow Co. renewed from main to curb stop.

18.0 Ft. - 3/4" copper tubing; 1 - same 3/4" curb stop;
1 stop box; 1 - 5/8" x 3/4" Fig. 413

1 stop box; 1 - $5/8"$ x $3/4"$ Fig. 413

DATE	BEF.	AFT.	REMARKS
------	------	------	---------

MAR 10 1981
6/7/84

Reamed

REAMED

[illegible]

CHARGE OUTS