

31-313

Remarks; 3/4-1" union installed 1.0 LF outside
curb stop

REMARKS

9/13/04 tap reamed

[illegible]