Service Killed APPLICATION No.: 7174	TAP CLEARED 8 23 5-13 85				
LOCATION: 10 Social St.	DATE	BEF.	AFT.	REMARKS	
OWNER: Joseph C. Simas	12/1/	76		Reamed	
MEASURES:					
H lead May 16,1892					
S from Social St. 41.3 ft.					
W from E line Harmony St. 6.9 ft.					
S from S line house 2.4 ft.		10			
Dec. 1, 1976 Renewed from the main to a point 3 ft.		3	100		
from the main.  3 ft 3/4" Copper tubing 5/8" x 3/4" Fig. 413					
5/8" x 3/4" lead to cop.					
adapt. XXS					
SEP 3 - 1982 Renewed from 6" outside curbstop to the					
property line. 10 ft3/4" copper; 3/4" curb stop; stop					
box; 2-5/8" x 3/4" lead-cop. adapt. XS;					
7/9/2009 Ace Asphalt Killed this service at the tap					
Installed new service off Social St. (# 33527)	7				
Inspected by Percy Reynolds - Contractor broke tap off + repaired with wrap-around.					
BRADBURY-WARING, INC.					

METER HISTORY									CHARGE OUTS	
DATE	SET	SIZE	MAKE	NUMBER	READING		TEST		REMARKS	
6-7-56		5/8		167980						
4										
								-		
						740				
	\ - 1							4.		
								17.		