APPLICATION No.: 8382	TAP CLEARED					
LOCATION: 197 Rivet St	DATE	BEF.	AFT.	REMARKS		
OWNER:	4/9/70	Ream				
MEASURES: 12/05/2018 Lead Service Replacement Program				,		
Phase 1, Contractor P Gioioso & Son						
Type CU, Diameter lin, Water pressure 95 (meter)					
Distance from main to curb stop (ft) 25						
Distance from curb stop to meter (ft) N/A Distance from curb stop to curb face (ft) 1.5						
Depth of service (ft) 4						
Total length of new pipe installed (ft) 25 Curb stop replaced: Yes size 1"						
Corporation replaced: Yes size 1"						
Ball valve replaced: No						

	APPLICATION No.:	8382	TAP CLEARED				
LOCATION: 197 Rivet S			DATE	BEF.	AFT.	REMARKS	1
OWNER: Joseph Frei		4-9-70			Reamed		
MEASURES:							
	H lead	Oct.11,1895					
W from	Hyacinthe St.	60.5 ft.					
S from N line	Rivet St.	9.1 ft.	-				
W from E lime	lime house	11.2 ft.					
Aug. 6, 1975 Renewed frourb stop.	to 6" outside						
6" - 3/4" Copper tubing 5/8" x 3/4" lead to copp							
Buffalo Stop Box	21						
April 9, 1970 Renewed from th	1			1			
2½ ft. of 3/4" copper tubing 1 wipe joint							
November 30. 1962 Renewed fro							
21 ft. of 3/4" copper tubing							
		-		-			
					-		
BRADBURY-WARING, INC.					1		

METER HISTORY								CHARGE	OUTS		
DATE	SET	SIZE	MAKE	NUMBER	READING	TEST REMARKS			-		
											. n .
		1.1									
11-30-6		3/41	Trident Mag	16325204							
6-7-72		3/4	Rock Mag	22048558							
					1						
				estable de la							
						-					
							19/11/11				
					200						
					- 76					3	
	-	-									
							7,1-5				
				A STANCE OF THE							
			123								
		-									
					1			- /			