

APPLICATION No.: 8877

## TAP CLEARED

LOCATION: 379 So. Second St.

OWNER: Manuel T. Lima

## MEASURES:

$\frac{1}{4}$ "  $\frac{3}{4}$ " H lead Nov. 25, 1896  
 S from South St. 362.1 ft.  
 E from Wline Second St. 4.7' ~~6.2 ft.~~  
 S from Nline house 9.0' ~~8.9 ft.~~

-----  
 October 9, 1968 Repaired leak-outside joint of curb stop; rewiped joint.

1 lb. wiping solder  
 -----

June 19, 1968 Renewed from  $\frac{1}{2}$  ft. outside curb stop to property line.  
 6 $\frac{1}{2}$  ft. of  $\frac{3}{4}$ " copper tubing used. Total.  
 1  $\frac{3}{4}$ " curb stop. Mueller 2 wipe joints  
 -----

July 13, 1967 Rewiped joint at tap.  
 -----

January 1976 Renewed from the new 8" main in Second St. to the property line.

14 ft. -  $\frac{3}{4}$ " Copper tubing  $\frac{3}{4}$ " Corporation  
 $\frac{3}{4}$ " Curb Stop Stop Box  
 5/8" x  $\frac{3}{4}$ " lead to copper adaptor  
 -----

7/6/82: Renewed from property line to the cellar. 14.0 ft.  
 $\frac{3}{4}$ " copper;  $\frac{3}{4}$ " x  $\frac{3}{4}$ " cop.-cop. adapt.  
 -----

[illegible]