

PLAN-1428

COUNTY STREET

Sawyer to Purchase.

50040

Plan and profile showing
Cause of water running
Continually in West gutter.
as complained of by abutters

