

CITY OF NEW BEDFORD

APPLICATION FOR LAYING BUILDING SEWER AND/OR DRAIN SERVICE

Application No 20119

permit # 23726
08/04/2005

April 4, 1977

Date

To the Mayor and City Council:

I hereby request that a building sewer and/or drain be laid for the premises at

4371 Acushnet Avenue

to connect with the sewer/drain in Acushnet Avenue street,
the same to be laid in the street and the surface repaired as directed by the Commissioner of
Public Works.

I hereby agree to pay at the office of the City Treasurer all cost of performing the above
work in the manner specified, in excess of the deposit made herewith, within 10 days after the
completion of the work.

It is understood and agreed that the deposit made with this application shall be applied
to the payment of the cost of performing the work done, and that any excess of deposit over the
cost shall be returned to me by the City Treasurer.

Witness

Signature of Property Owner

Address

Telephone No.

Plumber's Name

Requires separate entrance
for roof water

Address

Permits to Industrial and/or Commercial Applicants:

Permits can be issued to industrial and/or commercial applicants only upon receipt by
the Commissioner of Public Works of such supplemental information as may be required by
him concerning the quality and quantity of the proposed wastewater discharge.

This information was submitted by

Signature of Applicant (owner)

and approved by the Commissioner of Public Works on

Date

Commissioner of Public Works

Estimate and Deposit Requirement

Office of Commissioner of Public Works, April 4, 1977

My estimate of the cost of laying the building sewer and/or drain described in the above
application is

Assessed

Entrance charges Total deposit required 300.00

Commissioner of Public Works

Certificate of Issue

Office of City Clerk, April 4, 1977

The above application, accompanied by City Treasurer's receipt presented this day;
whereupon Permit No. 20119 was issued, and the Commissioner of Public Works
notified of the same.

City Clerk

Laid from main in street to property line.
Owner agrees to supply all necessary mater-
ials andtransite or iron pipe.

PAID, INSPECTION ONLY. TO BE ASSESSED.

April 4, 1977

Page 10 of 10

Acushnet Avenue

Acushnet Avenue

Acushnet Avenue is a residential street located in the Acushnet section of the City of New Bedford. The street is approximately 1.5 miles long and runs from the Acushnet River to the Acushnet River. The street is paved with asphalt and has a center line. The street is bordered by residential properties on both sides. The street is named after the Acushnet River.

The street is in good condition and there are no major problems. The street is well maintained and there are no major problems. The street is well maintained and there are no major problems. The street is well maintained and there are no major problems.

The street is in good condition and there are no major problems. The street is well maintained and there are no major problems. The street is well maintained and there are no major problems. The street is well maintained and there are no major problems.

The street is in good condition and there are no major problems. The street is well maintained and there are no major problems. The street is well maintained and there are no major problems. The street is well maintained and there are no major problems.

The street is in good condition and there are no major problems. The street is well maintained and there are no major problems. The street is well maintained and there are no major problems. The street is well maintained and there are no major problems.

The street is in good condition and there are no major problems. The street is well maintained and there are no major problems. The street is well maintained and there are no major problems. The street is well maintained and there are no major problems.

The street is in good condition and there are no major problems. The street is well maintained and there are no major problems. The street is well maintained and there are no major problems. The street is well maintained and there are no major problems.