

Service left turned on
NEW BEDFORD WATER WORKS.

SERVICE PIPE RETURN.

No. 10091

For Dartmouth Mill
No. Base Street.

43 ~~42~~ The expense for labor and materials to be paid
by the applicant is as follows:

.....	lineal feet of earth excavated at	cents per foot,	.	
.....	lineal feet of rock excavated at	cents per foot,	.	
<u>18 1/2</u>	lineal feet of ^{1 1/4} inch lead pipe at <u>36</u>	cents per foot,	.	<u>666</u>
.....	lineal feet of inch iron pipe at	cents per foot,	.	
.....	lineal feet of inch tin lined pipe at	cents per foot,	.	
<u>Backfilling</u>	<u>16 ft. trench</u>	<u>@ 11 1/2</u>		<u>184</u>
.....				
.....				
.....				
Proportion of other expenses for putting services into premises, .	.	.	.	<u>2</u>
Amount,	.	.	\$	<u>1050</u>

Office of Superintendent,

APR 11 1902 190 .

R. B. P. Boggeshall Superintendent.

WATER REGISTRAR'S OFFICE.

Mich. 28 1902.

To the Superintendent of the New Bedford Water Works:

Please put in a Service upon the premises described above, and make return of the expense of the same to this office.

James Hathaway Water Registrar.

10091

Dartmouth Mill
Core.

NEW BEDFORD WATER WORKS

SERVICE BILL RETURN

10091

Check

WATER REGISTRY OFFICE

Office of Water Registry

10091