NEW BEDFORD WATER WORKS.

SERVICE PIPE RETURN. No. 10540 For Joseph Orenberry	
Ho. Rear S. E. Ca Brownitch Beach of	reet.
The expense for labor and materials to be paid	
by the applicant is as follows:	
lineal feet of earth excavated at cents per foot, .	
lineal feet of rock excavated at cents per foot,	
lineal feet of 5" Hinch lead pipe at cents per foot, .	
lineal feet of inch iron pipe at cents per foot, .	
lineal feet of inch tin lined pipe at cents per foot,	
Connection of # 10272, made by anner	
Proportion of other expenses for putting services into premises,	

Office of Superintendent,

Chuquest 13, 1903. Superintendent.

WATER REGISTRAR'S OFFICE,

1903.

To the Superintendent of the New Bedford Water Works:

Please put in a Service upon the premises described above, and make return of the expense of the same to this office.

Hall away Water Registrar.

apple. Beatle st. Joseph Tumblay, Soughth of Ed. Bondutch.