

Barn
1st house
House

Connection of #4788

NEW BEDFORD WATER WORKS.

SERVICE PIPE RETURN.

No. 10601

For May G. Hoyer & Agnes C. Murphy
No. Rear 15 Pope Street.

The expense for labor and materials to be paid
by the applicant is as follows:

.....lineal feet of earth excavated at	cents per foot,	.
.....lineal feet of rock excavated at	cents per foot,	.
.....lineal feet of inch lead pipe at	cents per foot,	.
.....lineal feet of inch iron pipe at	cents per foot,	.
.....lineal feet of inch tin lined pipe at	cents per foot,	.

Connection made by owner Oct. 14 - 1903
3/4 in 4 lb lead pipe

In service book with 1905 services

Proportion of other expenses for putting services into premises, .
Amount, \$

Office of Superintendent,

October 14, 1903.

R. B. P. Boggeshall Superintendent.

WATER REGISTRAR'S OFFICE.

Oct. 12, 1903.

To the Superintendent of the New Bedford Water Works:

Please put in a Service upon the premises described above, and make
return of the expense of the same to this office.

C. Baylis Water Registrar.

#10601

Recd # 15-10-84
May 8. 1894
Wm. E. Murphy