New Bedford Water Works. No. 1087

RETURN OF SERVICE PIPE. Estate No. 38 Meyers (Stable) Put in by Service Pipe 3/4 inches diameter. July 12 to Cost to be paid by the City. Cost to be paid by the Proprietor. 14.5 lineal feet earth exc. at/9/2cts. 2 83 33. lineal feet earth excavated at/8/2cts.lineal feet rock excavated at lineal feet rock exc. at 14, / lineal feet lead pipe at 33cts. 4 63. 31. lineal feet lead pipe at 33 cts.lineal feet iron pipe at ...lineal feet iron pipe at Vapping Meino Vo: 10 90. Extre. Amount charged Proprietor,

16 38 Total Cost,

Amount paid by the city,.....

Su B Wheeler Superintendent.

SERVICE PIPE, No. 1087 Laid for Geo. Meyers Street. Expense to the City, Expense to the Proprietor, Total,

Water Registrar's Office,

New Bedford, 6/2/8 1872

To the Sup't of the N. B. Water Works:

Please put in a Service at the estate named on the back of this Order and return the expense thereof, &c., to my Office.

P. H. W and of Water Registrar.