Store.

1 fct.

1 w.c.

NEW BEDFORD WATER WORKS.

hose.

Connec. of # 10311

SERVICE PIPE RETURN.

No. 11243

| s, | | | |
|-------------------|--|--|---|
| 1115 Acush. Ave. | | (| Hreet |
| | to be paid | ! | |
| is follows: | | | |
| excavated at cer | nts per foot, | | |
| excavated at ce | ents per foot, | | |
| inch lead pipe at | ents per foot, | | |
| inch iron pipe at | cents per foot, | | |
| 1 | and materials states follows: excavated at centre and the centre a | and materials to be paid as follows: excavated at cents per foot, excavated at cents per foot, ench lead pipe at cents per foot, | and materials to be paid s follows: excavated at cents per foot, excavated at cents per foot, ench lead pipe at cents per foot, |

lineal feet of inch tin lined pipe at cents per foot

made in cellar for store next north (no pipe under-

Office of Superintendent,

R. J. Loggeshall Superintender
WATER REGISTRAR'S OFFICE.

Nov. 1st, 1905. 190 .

To the Superintendent of the New Bedford Water Works:

Please put in a Service upon the premises described above, and make return of the expense of the same to this office.

C. Baylies Water Registrar.

11243 Connection of # 10311-#1115 Acush. Are. John Kalis