NEW BEDFORD WATER WORKS.

6-8-10"

SERVICE PIPE RETURN.

No. 11646

For Nonquitt Spinning Co.,
Co. E. side Belle. Ave. N. of Belle. Road Street.
The expense for laker and materials to be paid
lineal feet of earth excavated at cents per foot, lineal feet of rock excavated at cents per foot, lineal feet of 6-8-10 inch lead pipe at cents per foot, lineal feet of inch iron pipe at cents per foot, lineal feet of inch tin lined pipe at cents per foot Nanquitt Spinning Co. pays whole lill Landetails of hill, see Bill Book, pg. 28-
Proportion of other expenses for putting services into premises . Amount,
Office of Superintendent, May 17th, 1907. Superintendent. WATER REGISTRAR'S OFFICE. Jan. 23d, 1907. 190
To the Superintendent of the New Bedford Water Works: Please put in a Service upon the premises described above, and make

return of the expense of the same to this office.

C. Baylies Water Registrar.

wide Dalle Water

.Top. 884, 1907.

, .or animal daluphull

S. side Della, Ava.

E S. Belle. Are., N. of 13elle. Rongrett Huming E.

.. of galanige Jilupack