NEW BEDFORD WATER WORKS.

4in

SERVICE PIPE RETURN.

No. 11647

For Nonquitt Spinning Co.,
Co. E. side Belle. Ave., N. of Belle. Road Sheel.
The expense for laker and materials to be paid
lineal feet of earth excavated at cents per foot, lineal feet of rock excavated at cents per foot, lineal feet of \(\psi\) inch lead pipe at cents per foot, lineal feet of inch iron pipe at cents per foot, lineal feet of inch tin lined pipe at cents per foot Nonquitt Shinning Co. hays while lill Lineals of lill see Bill Bads, Pg. 28
Proportion of other expenses for putting services into premises
Office of Superintendent,
R.b.P. boggeshall Superintendent.
WATER REGISTRAR'S OFFICE.
Jan. 23d, 1907. 190
To the Superintendent of the New Bedford Water Works:
Please put in a Service upon the premises described above, and make return of the expense of the same to this office.

10. Baylies Water Registrar.

Choiler & fixtures.

. m. tell

a herriaarya i

Monquitt Spinning Co.,

P. side Belle. Ave., M. of Relle. Road

S. Belle. Dec. N. of Nonquitt Spring &

Beller & Pistures,

Manguist Spinning Co.

R. side Belle. Ave., N. of Selle. Road