New Bedford Water Works. No. 1175

RETURN OF SERVICE PIPE.

Testata No AR Mariatas

Estate No.	1	10	h hollen	Street	, for
Put in by Giffor	U.y	, SI	Allen		
Service Pipe 78 inche	s di	amei		the	872
				······································	UIZ
Cost to be paid by the City.			Cost to be paid by the Proprietor.		
12lineal feet earth exc. at 19/2cts.	12	34	2.5. lineal feet earth excavated at 18/2cts.	/	46
2,5 lineal feet rock exc. at/42cts.	13	55	lineal feet rock excavated at cts.		
4. / lineal feet lead pipe at 38 cts.	5	36	3.5 lineal feet lead pipe at 38 cts.	V/	33
lineal feet iron pipe at cts.			lineal feet iron pipe at cts.		
apping Main & C., Less	10	90	Estra	2	00
Less.	22,	15			
			Amount charged Proprietor,	V.3	79
Amount paid by the city,	20	15	Total Cost,	23	94

Gu B Wheeler Superintendent.

Laid fo He 49 Expense	CE PIPE, No. 1/75 r My clb. Allen Street 187 e to the City, to the Proprietor,	To
Total,	-	=

Water Registrar's Office,

New Bedford, 9/7 1872

To the Sup't of the N. B. Water Works:

Please put in a Service at the estate named on the back of this Order and return the expense thereof, &c., to my Office.

Water Registrar.