

120 Tallman Street.

5 fam.
7 fets.
5 w.c.
1 b.t.

NEW BEDFORD WATER WORKS.

Connection of
Appli[#] 11753

SERVICE PIPE RETURN.

No. 12516

For U. Vigneault,

No. W. S. Bowditch, N. of Tallman Street.

The expense for labor and materials to be paid
by the applicant is as follows:

..... lineal feet of earth excavated at	cents per foot,
..... lineal feet of rock excavated at	cents per foot,
..... lineal feet of $5/8$ " inch [#] lead pipe at	cents per foot,
..... lineal feet of inch iron pipe at	cents per foot,
..... lineal feet of inch tin lined pipe at	cents per foot,

Application 11753 ^{supply to barn in rear} passed through cellar of new house built
on front of lot. A 4 in main stop was placed in this
pipe 18 in inside of cellar wall and connection for new
house made with this pipe by owner using 5/8" H. lead pipe

February 15-1909

Proportion of other expenses for putting services into premises .

Amount \$

Office of Superintendent,

R. b. P. Boygshall ^{February 15 1909} Superintendent.

WATER REGISTRAR'S OFFICE.

Jan. 11, 1909. 190

To the Superintendent of the New Bedford Water Works:

Please put in a Service upon the premises described above, and make
return of the expense of the same to this office.

C. Baylies Water Registrar.
per W. P.

X

appli. #12516 c
 Brinditch, W. L., N. of Tallman
W. Vigneault

NEW BEDFORD WATER WORKS

SERVICE PIPE RETURN

NO.

2110

1/2 inch iron pipe at 100 ft. 100 ft.
 1/2 inch iron pipe at 100 ft. 100 ft.
 1/2 inch iron pipe at 100 ft. 100 ft.
 1/2 inch iron pipe at 100 ft. 100 ft.
 1/2 inch iron pipe at 100 ft. 100 ft.
 1/2 inch iron pipe at 100 ft. 100 ft.
 1/2 inch iron pipe at 100 ft. 100 ft.
 1/2 inch iron pipe at 100 ft. 100 ft.
 1/2 inch iron pipe at 100 ft. 100 ft.
 1/2 inch iron pipe at 100 ft. 100 ft.

Office of Superintendent

WATER RESISTANCE OFFICE

Superintendent

100

100