## New Bedford Water Works. No.1283

RETURN OF SERVICE PIPE.

|  | County -                           |         | t, for |
|--|------------------------------------|---------|--------|
| Put in by 6:4<br>Service Pipe 378 inches dia | meter. May 2 th                    |         | 1873   |
| Cost to be paid by the City.                 | Cost to be paid by the Proprietor. |         |        |
| Ineal feet earth exc. at cts.                |                                    |         | 69 x   |
| /8.8 lineal feet lead pipe at cts.           | lineal feet rock excavated at cts. | 1       | 20x    |
| lineal feet iron pipe at cts.                | Entering primises                  | 2       | OOX    |
| `  |                                    |         |        |
|  |                                    |         |        |
|  | Amount charged Proprietor,         | 3       | 894    |
| Amount paid by the city,                     | Total Cost,                        |         |        |
| 0  | Su B Meeler super                  | rintend | lent.  |

SERVICE PIPE, No. 12/83

Laid for

Showas 13. Triff

61. County Street.

1873

Expense to the City,

Expense to the Proprietor,

Total, - - -

Water Registrar's Office,

New Bedford, 5/1 1873

To the Sup't of the N. B. Water Works:

Please put in a Service at the estate named on the back of this Order and return the expense thereof, &c., to my Office.

OHHawlandfur Water Registrar.