New Bedford Water Works. No. 1336

RETURN OF SERVICE PIPE.

KE I	URN OF SERVICE PIPE.			
Estate No. 58	/ Hill }	treet	, for	
Benj	anin F. Brownell			
Put in by City.				
Service Pipe 5/8 inches diameter. 6 mm 5 1873				
0 11 1 11 11 11 11 11 11	Cook to be weld by the Developer			
Cost to be paid by the City.	Cost to be paid by the Proprietor.			
2/ lineal feet earth exc. at cts.	6.3 lineal feet earth excavated at 23cts.	1	30	
3 lineal feet rock exc. at cts.	lineal feet rock excavated at cts.			
35. Sineal feet lead pipe at cts.		2	32	
lineal feet iron pipe at cts.	Enterniz premises	2	00	
			V	
	Amount charged Proprietor,	3-	82	
Amount paid by the city,	Total Cost,			

Un B Wheeler superintendent.

SERVICE PIPE, No. 1336
Laid for
Brug H Brownill
Brug H Brownill 58 Hill street.
1873
Expense to the City,
Expense to the Proprietor,
Total,

Water Registrar's Office,
New Bedford, 5/3/ 1873

To the Sup't of the N. B. Water Works:

Please put in a Service at the estate named on the back of this Order and return the expense thereof, &c., to my Office.

PHH wlandford